ECS Configuration Change Request

Page 1 of 22 Page(s)

1. Originator	2. Log Date:	3. CCR #: 03-0275		4. Rev:	5. Tel:	6. Rm #:	7. Dept.
R. Haynes	04/16/03	03-0275			925-0932	2110F	SED
8. CCR Title: Remove MODAPS HiPPI and MCST Connections							
9. Originator Signature/Date			п		11. Type:	12. Need Date: 5/2/03	
R. Haynes /s/ 04/14/03			" CCR				
13. Office Manager Signature/Date			14. Category of Change:		_	15. Priority: (If "Emergency" fill in Block 27).	
Jim Mather /s/ 04/14/03			Update ECS Baseline Doc. fill in Block 27). Routine				
checklist):			17. Schedule 18. CI(s) Affected:ISS Impact: None				
19. Release Affected by this Change: 20. Date due			to Customer: 21. Estimated Cost:				
N/A		N/A			one - Under 100K		
22. Source Reference:	□NCR (attach) □ Action	on Item T	ech Ref.	□GSF	C		
23. Problem: (use additional Sheets if necessary) 1. The HiPPI connecton bwtween the GSFC DAAC and MODAPS via the Firewall is no longer being used. 2. The MCST connection has been removed.							
 24. Proposed Solution: (use additional sheets if necessary) 1. Remove the MODAS HiPPI connection. 2. Remove the MCST connection. 							
25. Alternate Solution: (use additional sheets if necessary) None							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Network documentation will be incorrect.							
27. Justification for Emergency (If Block 15 is "Emergency"):							
28. Site(s) Affected: □EDF □PVC □VATC □EDC □ GSFC □LaRC □NSIDC □SMC □AK □JPL □EOC □ IDG Test Cell □Other							
29. Board Comments:				30. W	ork Assigned To	o: 31. CCR (Closed Date:
32. EDF/SCDV CCB Chair (Sign/Date): Di	•	oproved	App/Com	n. Disapproved	Withdraw Fwd	ESDIS ERB
33. M&O CCB Chair (Sign/I Gary Gavigan /s/ 4/22/03	Date): Di	sposition: Ap		App/Com	. Disapproved	Withdraw Fwd/	ESDIS ERB
Fwd/ECS							
A4. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS							

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O